

Bracket Supported Tiled Porches



- Fixing to have been considered in the design
- Information to be held by Site Manager and Installer

Downlighters



- Insulation Separator
- 4.5w LED Bulb (low heat)
- 6 light fittings operated from one switch [if under the 2013 regulations]



- Problem identified - loose connections (vibration / heat build-up)
- Excessive heat in plastic boxes can cause ignition / fire
 - Reinforce controls with installers
 - Introduction of metal encased units – July 2015

- Small child removed white plastic cap from 'sprung nickel plated door stop'. Swallowed it - almost choking.
- New specification - deeper end cap (more difficult to remove) and air hole to allow continued breathing.



- HSE drive for implementation:
 - RPE
 - ‘Face-fit’ Testing
 - Extraction Equipment
- HBF / HfS
 - Briefing
 - Information Pack for Contractors
 - Tool Box Talks for Operatives
 - Work with suppliers re best / cost effective equipment