


Ian Gray



FROM THE GROUND UP

Combining our highly experienced team and state of the art equipment, WM Donald strives to deliver your services in a compliant and efficient manner from the ground up

W M Donald Ltd
Civil Engineering Contractors
Marrlaine, Netherley
Stonehaven, AB39 3QN
info@wmdonald.co.uk
01569 730590



Health & Safety - Issues

- Main causes service strikes:
 - Inadequate planning
 - Rush to complete job/ task
 - Lack of information/ inaccurate information (drawings)
 - Poor excavation techniques
 - Lack of care by Operatives
 - Limited use of detection equipment
 - Poor plant control/ lack of visibility



NJUG – Disposition











-  250 diam Water Main
-  180 Gas Main
-  HV Electric
-  LV Electric
-  Street Lighting
-  British Telecom
-  Private Comms
-  Service Connections
-  Pedestrian Crossing



FIGURE 1 - Recommended Positioning of Utility Apparatus in a 2 metre Footway



BT Boxes



Future Service Connections





























Any Questions?

W M Donald Ltd

Civil Engineering Contractors
Marrlaine, Netherley
Stonehaven, AB39 3QN
info@wmdonald.co.uk
01569 730590

